

General Environmental Incident Summary

Incident: 4184 **Date/Time Notice:** 8/2/2016 **DEM Incident No:** 10996

Responsible Party: City of Crosby

Date Incident: 8/2/2016 **Time Incident:** **Duration:**

County: Divide **Twp:** 163 **Rng:** 97 **Sec:** 29 **Qtr:**

Lat: 48.94325 **Long:** -103.29620 **Method:** Navigation quality GPS

Location Description: 12 Main Street North, Crosby, ND, 58730

Submitted By: Jody Gunlock

Affiliation:

Address: PO BOX 49

City: Crosby

State: ND

Zip: 58730

Received By: Robin Schiermeister

NDDoh

Contact Person:

PO BOX 49

Crosby, ND 58730

Distance Nearest Occupied Building: 5 Feet

Release Contained: No

Type of Incident: Tank Leak

Description of Released Contaminant: heating oil

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

During renovation of the streets of Crosby this tank was found lying in contaminated soil. The tank was found to have holes in it which is believed to be the cause.

Risk Evaluation:

none

of Fatalities: 0

of Injuries: 0

Affected Medium: 05 - air and soil

Potential Environmental Impacts:

none

Action Taken or Planned:

The soil was excavated and stockpiled by the landfill till permission is given for it to be cultivated into the soil.

Wastes Disposal Location: It will be cultivated into the soil at a later date.

Agencies Involved:

Updates

Date: 8/4/2016 ***Status:*** Reviewed - Assigned to NDDoH Division

Author: Souder, Taylor

Updated Volume:

Notes:

Further follow-up needed.